# MATERIAL SAFETY DATA SHEET

| Company BRALCO METALS as21 CANFORD ST.                                     | Issue Date<br>NOVEMBER 25, 1985<br>REVISED<br>MARCH 1, 1988       | Identification Number SILICON BRONZE LEADED BRONZE |  |
|--|---|--|--|
| PICO RIVERA, CALIFORNIA 90880  Teade Name (Common Name or Synonym)  BRONZE | ALUMINUM BRONZE  Emergency Phone Number 213-582-2272 213-723-3601 |  |  |
| Chemical Name  | Formula   | DOT Identification Number<br>NA                    |  |

## I. INGREDIENTS

| ASE METAL, ALLOYING ELEMENTS AND METALLIC COATINGS | CAS #     | % COMPOSITION BY WEIGH | IT (1)  | OSHA PEL   | ACGIH TLV (mg/m²) |
|--|-----------|------------------------|---------|------------|-------------------|
| Base Metal   | CAS #     |                        | OSHA PE | L          |                   |
| Copper (Cu)  | 7440-50-8 | 70-99                  | 1       | 1 (Dust &  | Mist)             |
| Alloying Elements                                  |           |                        |         | •          | •                 |
| Nickel (Ni)  | 7440-02-0 | 0-14                   | 1       | 1          |                   |
| Aluminum (Al)                                      | 7429-90-5 | 0-14                   | N.E.    | 10         |                   |
| Iron (Fe)  | 7439-89-6 | <5                     | 10      | 5 (As Iron | n Oxide)          |
| Silicon (Si)                                       | 7740-21-3 | < 4                    | 15      | 10 (Total  | •                 |
| Manganese (Mn)                                     | 7439-96-5 | < 4                    | 5       | 5 (As Dust | t-Ceiling)        |
| Cohalt (Co)  | 7440-48-4 | <2                     | .1      | .1`        |                   |
| Tin (Sn)   | 7440-31-5 | <1                     | 2       | 2          |                   |
| Zinc (Zn)  | 7440-66-6 | <1                     | N.E.    | 5 (As Fume | e)                |
| Leaded Alloys                                      |           |                        |         | •          | •                 |
| Lead (Pb)  | 7439-92-1 | <1                     | .05     | .15 (Dust  | & Fume)           |
| • •  | · -       |                        |         |            | •                 |

## II. PHYSICAL DATA

| Material is (At Normal Conditions). |               | Appearance and Odor RED/GOLD METALLIC ODORLESS |   |                     |                       |                     |                 |
|-------------------------------------|---------------|--|---|---------------------|-----------------------|---------------------|-----------------|
| 🖺 Liquid 🚍 Solid 🗍 Gas              | ☐ Other       | <del></del>                                    |   |                     | MED/GOLI              | THE TALERO ODONELOG | <del></del>     |
| Acidity/Alkalinity                  |               |  |   |                     | •                     |                     | Vapor Pressure  |
|                                     | Melting Point | > 1700   | F | Specific Gravity (F | H <sub>2</sub> O - 1) | > 7                 | (mm Hg at 20 C) |
| pH - NA                             | Boiling Point | NA   | F | Solubility in water | (% by weight)         | NA                  | NA NA           |

#### III. PERSONAL PROTECTIVE EQUIPMENT

| Respiratory Protection NIOSH/MSHA APPROVED DUST & FUME RESPIRATOR SHOULD BE USED TO AVOID EXCESSIVE INHALATION OF PARTICULATES WHEN EXPOSURE EXCEEDS TLV'S | Hands, Arms and Body, PROTECTIVE GLOVES ARE RECOMMENDED DURING HANDLING OF FINES EXPOSURE                      |
|--|--|
| Eyes and Face SAFETY GLASSES OR GOGGLES SHOULD BE UTILIZED AS REQUIRED BY EXPOSURE   | Other Clothing and Equipment OTHER PROTECTIVE EQUIPMENT SHOULD BE UTILIZED AS REQUIRED BY THE WELDING STANDARD |

# IV. EMERGENCY MEDICAL PROCEDURES

IF EXPOSED TO EXCESSIVE LEVELS OF METAL FUMES, REMOVE TO FRESH AIR, SEEK MEDICAL AID IMMEDIATELY.

EYES: FLUSH WITH WATER FOR AT LEAST 15 MINUTES.



#### V. HEALTH/SAFETY INFORMATION

|                    |   | ······································ | ———————  | ETT INFORMATION  |   |  |  |
|--------------------|---|--|--|--|---|--|--|
| BURNI              | NG, WELDING, SAWING<br>R EXPOSURE HAZARD  | 3. BRAZING AND GRINDING M              | IAY RELEASE FUMES /                                | N, INGESTION OR CONTACT HAZARD. HOWEVER, OPERATIONS SUCH AS AND/OR DUSTS WHICH MAY PRESENT HEALTH HAZARDS IF TLV'S ARE EXCEEDED.               |   |  |  |
| ,                  | Inhalation of<br>cause metal fo   | high concentration                     | ons of freshly<br>erized by a me                   | e irritation of eyes and respiratory system.<br>formed oxide fumes of copper and lead may<br>tallic taste in the mouth, dryness of the         |   |  |  |
| 1                  | Symptoms of le  | ead poisoning incl                     | lude abdominal                                     | y result in lead-induced systemic toxicity.<br>cramps, anemia, muscle weakness and headache.<br>nges, kidney damage, CNS damage, and reproduc- |   |  |  |
|                    | Toxicology Pro<br>sensitization   | ogram (NTP). Expo                      | osure to high<br>ammation and/o                    | n carcinogens as prepared by the National concentrations of dust and fumes can cause or ulceration of upper respiratory tract and              |   |  |  |
|                    |   | iological studies<br>found no increas  |  | elt.ing and working alloys containing nickel/<br>ncer.   |   |  |  |
| SUSP               | ECTED CANCER AGEN   | NT? NO. THIS PRODUCTS                  |  | OT FOUND IN THE LISTS BELOW  | · |  |  |
| Fire and Explosion | Flash Point NA F  | Auto ignition Temperature              | Flammable Limits<br>in As<br>Lower %<br>Upper NA % | Extinguishing Media NA   |   |  |  |
|                    | Fire and Explosion Hazards DUST HAZARD EXISTS UNDER FAVORING CONDITIONS OF SMALL PRACTICE SIZE. DISPERSION IN AIR AND STRONG IGNITION SOURCE MAY RESULT IN AN EXPLOSION  RA  Extinguishing Media not to be used  NA |  |  |  |   |  |  |
| Ş                  | Stability Incompatibility (Materials to Avoid) MERCURY, AMMONIA, ACETYLENE, ACIDS   |  |  |  |   |  |  |
| Reactivity         | Conditions to Avoid EXPOSURE DURING STORAGE TO STRONG ACIDS, BASES OR OXIDIZING AGENTS  |  |  |  |   |  |  |
| <b>.</b>           | Hazardous Decomposition Products  TOXIC GASES, AEROSOLS & VAPORS MAY BE RELEASED IN A FIRE INVOLVING COPPER ALLOYS IF FUMES OF OTHER COMPOUNDS OR CONTACTING MATERIALS ARE INVOLVED                                 |  |  |  |   |  |  |
|                    |   |  | VI. ENVIR  | ONMENTAL   |   |  |  |
| Spill              | or Leak Procedures  |  | · · ·  | NA ·   |   |  |  |
| Was                | te Disposal Method  | ACCORDING TO LO                        | ICAL, STATE AND FED                                |  |   |  |  |
|                    | <del></del>   | 1                                      | VII. ADDITION                                      | AL INFORMATION   |   |  |  |
|                    | /FNTILATION LOCAL S   | EXHAUST VENTILATION SHOW               | 8 D 96 1178 1750 WUS                               | N WELDING BURNING  |   |  |  |
|                    |   | INDING OR MACHINING WHEN               |  |  |   |  |  |
|                    | •   | TONS SHOULD BE TAKEN FO                |  |  |   |  |  |
| ٠,                 | WHICH MAY ORIGINATE   | E FROM COMPONENTS OF W                 | ELDING ROD   |  |   |  |  |
| 4                  | ARG OR SPARK GENER  | ATED WHEN WELDING OR B                 | URNING COULD BE A                                  | SOURCE   |   |  |  |
|                    | OF IGNITION FOR COM   | MBUSTABLE AND FLAMMABLI                | E MATERIALS  |  |   |  |  |